
INSTALLATION INSTRUCTIONS

FLAT PANEL DISPLAY STATIC MOUNT PSM-2126⁽¹⁾



- (1) LCD Display Static Mount
- (1) Latching Flag
- (4) M8 x 25mm Phillips Head Cap Screws
- (4) Mounting Buttons-


- (1) 10-24 x .5 Phillips Flat Head Screw
- (1) Nylon Washer
- (1) 10-24 Nylock Nut

BEFORE PROCEEDING: Unpack the carton, verify contents shown in Figure 1 and read installation instructions completely. If you are missing any of the listed components, please contact Customer Service at 1-800/582-6480.

CAUTION!

Flat Panel Displays are Extremely Fragile.

- 1. Attach latching flag to mount using the 10-24 Phillips flat head screw, Nylon washer, and Nylock nut (see Figure 2). Tighten until friction will hold the flag in place.
- 2. Attach mounting buttons to display using the M8 screws provided (see Figure 3 & Figure 4).



WARNING

ALL COMPONENTS MUST BE SECURELY FASTENED TO A STRUCTURAL MEMBER CAPABLE OF SUPPORTING 4 TIMES THE COMBINED WEIGHT OF ALL COMPONENTS PLUS THE EQUIPMENT BEING MOUNTED. IF IT CANNOT SUPPORT THIS WEIGHT, THE STRUCTURE MUST BE REINFORCED.

THE MAXIMUM WEIGHT TO BE INSTALLED ON THE MOUNT IS 150 POUNDS (68.04 KG).

- 3. Securely anchor the static mount to wall study or supporting framework (see WARNING).
- 4. Make sure the flag is lowered to the side before attempting to place the display on the mount.
- 5. With the aid of another person, lift the display up to the mount, align the mounting buttons with the teardrop slots in the mount, and set the display into place (see Figure 5).
- 6. Position (raise) the flag to secure the display to the mount.




Figure 5